

**Remarks**

No new matter is believed to be added by this amendment.

The Examiner is respectfully requested to enter these amendments. Applicant is unaware of any Office Action at the time of submission of this Amendment After Allowance.

Date: September 26, 2006

Respectfully submitted,

/David Peterson/  
David Peterson  
Attorney for Applicant  
Reg. No. 37,909  
Telephone: (510) 271-7521  
Facsimile: (510) 271-1652

Attachments: Exhibit A – Annotated Version of Modified Specification To Show  
Changes Made

360.76A

J:\PT (new)\ACB (New)\Patent\Amendment after allowance 360.76a.doc

**ANNOTATED VERSION OF MODIFIED SPECIFICATION**  
**TO SHOW CHANGES MADE**

Pursuant to 37 C.F.R. §1.121, amend the following paragraphs of the specification by deleting that language which is enclosed within brackets (“[ ]”) and by inserting that language which is underlined (“      ”).

Page 3, lines 27 and 28:

Fig. 1 is a [color] photograph showing a clean vitreous surface (toilet bowl) after single treatment with the inventive liquid cleaner after 78 flushes.

Page 3, lines 29 and 30:

Fig. 2 is a [color] photograph showing an iron stained vitreous surface (toilet bowl) after no treatment (Spike) after 78 flushes.

Page 3, lines 31 and 32, and Page 4, line 1:

Fig. 3 is a [color] photograph showing an iron stained vitreous surface (toilet bowl) after yet another treatment with a commercial toilet bowl cleaner after 78 flushes.

Page 4, lines 2 through 4:

Fig. 4 is a [color] photograph showing a clean vitreous surface (toilet bowl) after 78 flushes, in which the flush water has been softened and no treatment has occurred (Control).

Page 4, lines 5 and 6:

Fig. 5 is a [color] photograph showing a clean vitreous surface (toilet bowl) after single treatment with the inventive cleaner after 108 flushes.

Page 4, lines 7 and 8:

Fig. 6 is a [color] photograph showing an iron stained vitreous surface (toilet bowl) after no treatment (Spike) after 108 flushes.

**ANNOTATED VERSION OF MODIFIED SPECIFICATION**  
**TO SHOW CHANGES MADE**

Page 4, lines 9 through 11:

Fig. 7 is a [color] photograph showing an iron stained vitreous surface (toilet bowl) after treatment with a commercial toilet bowl cleaner after 108 flushes.

Page 4, lines 12 through 14:

Fig. 8 is a [color] photograph showing a clean vitreous surface (toilet bowl) after 108 flushes, in which the flush water has been softened and no treatment has occurred (Control).

Page 16, lines 22 through 24:

Considering the [color] photographs Figs. 1-8, it can be demonstrably seen that the Invention provides outstanding residual stain repellency after a single daily treatment.